

Pulse Oximeter

Wellue®
Powered by Viatom


Checkme™ O2 Max



Heart
Rate



Oxygen
Saturation



Perfusion
Index

Innovative

| Wearable

| Adaptable

| Reliable

Pulse Oximeter

Monitor oxygen level anytime, anywhere



Features

- Comfortable wearing experience
- Track and record oxygen level and heart rate
- Smart vibrate or beep triggered by low SpO2
- Built-in rechargeable battery for overnight use
- Sync real-time data with App via Bluetooth
- Support remote monitoring by wireless module



Overnight tracking



Precise measurement



Beep/Vibration reminder



Free APP




Cloud storage


Applicable scene



Chest tightness




Dizziness and fatigue



Snoring with apnea



Daytime sleepiness



Tired after waking up



Decline of memory

Continuous monitoring

Track Your Oxygen Levels

Once a low oxygen level or an abnormal heart rate is detected, Checkme O2 Max will smart vibrate or beep immediately to remind you.

After syncing the recording data to App, detailed analysis and trends of your oxygen level and heart rate can be reviewed.



Specifications

Blood oxygen level range

70%-99%

Blood oxygen accuracy

80-99%: $\pm 2\%$, 70-79%: $\pm 3\%$

Pulse rate range

30 to 250 bpm

Pulse rate accuracy

± 2 bpm or $\pm 2\%$

Remind source

Low oxygen level, high/low pulse rate

Dust and waterproof rating

IP22

Recorded parameters

Blood oxygen level, pulse rate, exercise

Weight

25g

Device size

50mm x 39mm x 14mm

Built-in memory

4 sections, up to 10 hours each section

Battery

Rechargeable lithium battery

Use time 68-80 hours

Wireless

Bluetooth 4.0 BLE

Compatibility

iOS 9.0+ ; Android 5.0+